

The AkzoNobel logo is displayed in a bold, blue, sans-serif font in the upper right corner of the image. The background of the entire image is a photograph of a large industrial building with blue corrugated metal siding and a long row of windows. A white banner with the AkzoNobel logo is visible on the side of the building. In the foreground, there is a paved area with yellow diagonal stripes and a blue door with yellow handrails. The sky is clear and blue.

AkzoNobel

A white, semi-transparent rectangular box is overlaid on the lower left portion of the image. It contains the text 'Community Forum' and 'Feb 16th, 2022' in a bold, black, sans-serif font. The background behind the text is the same industrial building and sky as the rest of the image.

Community Forum
Feb 16th, 2022

Agenda

Odour Update

Air Monitoring Results

Noise Update

Reporting of Complaints

Questions & Discussion

Odour Updates



- Commissioned & Operational from December 2021
- Initial Golder monitoring results conducted 13th Dec
- Further balancing and finetuning of RTO setup Jan 2021
- Follow – Up Golder Monitoring planned Wk 3 Feb
- Carbon bed filter remains in place as standby for RTO

Paint Plant Update

- ↗ Golder conducting weekly boundary Odour sampling
- ↗ Completed a review of Paint Plant Odour & Emission sources and final report submitted to EPA in January
- ↗ Recommendations from Golder report are being investigated and scoped to remove VoC & Odour sources from Paint Plant

Air Monitoring Updates

Fence line air quality monitoring for VOCs



- ❑ Monitoring undertaken by Golder Associates' NATA-accredited air quality team
- ❑ 8 fence line monitoring locations
- ❑ Monitoring ongoing from March – December
- ❑ Monitoring continues to show levels of VoC's significantly below threshold values

Noise Review

Acoustic Wall


➤ Acoustic Wall

- Awaiting Council planning approval (submissions for objections closed 28th Jan)
- Engineering, scoping & working drawings underway
- Building permit and tendering process
- Installation will take approx. 12 – 16 weeks
- We welcome neighborhood feedback on wall design and look



Noise Review

- Powder Plant continues to cease operations at night.
- Powder Mill fan upgrade has improved overall noise levels
- Replacement gearbox of DT 5 completed
- Noise reduction plan completed and being implemented
- Focus on engineering controls to eliminate noise sources
- Seek community feedback to ensure we prioritize improvement actions.



Reporting of Complaints

- ↗ First Contact site personnel have received training in dealing with reported complaints
- ↗ Response to some complaints not as expected and further training completed
- ↗ Complaints received have been responded to
- ↗ We continue to encourage community members to report issues directly to AkzoNobel so that we can investigate at the time of reported incident.

Phone **03 9313 4555**

Email reception.sun@akzonobel.com

Xmas Shutdown Works



- Removal & recladding of asbestos sheeting with Colourbond
- Roadway Upgrade
- Routine Shutdown Maintenance

- Thank you to Neighbours along Barwon Avenue for putting up with additional traffic over a number of days

Powder Building wall on Barwon Ave



Questions & Discussion

Thank you